This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.


Architectural Panel Center Sectio




Architectural Panel End Section ...




urn Secti Panel I **Architectural** |




Architectural Panel Window!




Architectural Panel Bottom Section




Architectural Panel Bottom Section




Wall Panel Section ...




Architectural Panel @ 3-Sided Rib Mid




Architectural Panel @ 4-Sided Mid Rib








Architectural Panel


(2) Thermally Broken Closed-End Rib Joint














F19. 15


Hardwall Panel (2) Horizontal Joint







Load-Bearing Wall Panel









Multi-unit Residential Wall Pane @ Middle Rib




Multi-unit Residential Panel @ End Rib



Multi-unit Residential Panel @ Corner Ribs



Multi-unit Residential Panel



Multi-unit Residential Panel 85 7 6 @ Bottom Rib 8